Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	15844	flange.ab. and seal\$5	USPAT	OR	OFF	2005/05/31 10:08
S2	727	"bolt holes" and S1	USPAT	OR	ON	2005/05/31 13:39
S3	0	2@py<="2005"	USPAT	OR	OFF	2005/05/31 10:11
S4	2	(deton\$ deflag\$) and S2	USPAT	OR	OFF	2005/06/01 08:41
S5	294	(277/614).CCLS.	USPAT	OR	OFF	2005/05/31 14:23
S6	532	(277/616).CCLS.	USPAT	OR	OFF	2005/05/31 14:44
S7	505	S6 not S5	USPAT	OR	OFF	2005/05/31 14:23
S8	166	flange and S7	USPAT	OR	OFF	2005/05/31 14:44
S9	324	(277/625).CCLS.	USPAT	OR	OFF	2005/05/31 14:44
S10	64	flange and S9	USPAT	OR	OFF	2005/05/31 14:44
S11	59	S10 not S8	USPAT	OR	OFF	2005/05/31 14:45
S12	4	122/235.18.ccls. and flange	USPAT	OR	OFF	2005/05/31 14:50
S13	47	122/379.ccls. and flange	USPAT	OR	OFF	2005/05/31 14:55
S14	7	122/405.ccls. and flange	USPAT	OR	OFF	2005/05/31 14:55
S15	6	S14 not S13	USPAT	OR	OFF	2005/05/31 14:55
S16	2	(("4741292") or ("5741130")).PN.	USPAT	OR	OFF	2005/06/01 08:40
S17	47	(deton\$ deflag\$) and "122"/\$.ccls.	USPAT	OR	OFF	2005/06/01 08:46
S18	10246	(deton\$ deflag\$ deslag\$).bsum. not "122"/\$.ccls.	USPAT	OR	OFF.	2005/06/01 08:47
S19	21	clean\$ and (lance sootblower) and S18	USPAT	OR	OFF	2005/06/01 08:50
S20	844	(mount\$ near2 flange).ab. and hole\$1 and bolt\$2	USPAT	OR	ON	2005/06/01 08:51
S21	15844	flange.ab. and seal\$5	USPAT	OR	OFF	2005/06/01 08:51
S22	727	"bolt holes" and S21	USPAT	OR	ON	2005/06/01 08:51
S23	768	S20 not S22	USPAT	OR	ON	2005/06/01 08:51
S24	4	(("6684823") or ("3216046") or ("4359800") or ("4765394")).PN.	USPAT	OR	OFF	2005/06/01 13:38
S25	1	("4545329").PN.	USPAT	OR	OFF	2005/06/01 14:07